


Wire length: 55cm  
Crimp the corresponding ferrule/terminal on both ends of the wires.  
Place the terminals in the correct location of the connector housing



	Title: <b>PSU to PCBA Cable Assembly</b>	
	Drawn: TLa	Number: 1.
Checked: TSt	Date: 21-9-2017	Rev: MLA-0387-C2 PA0
File: MLA-0387-C2.SchDoc	Sheet: 1 of 1	